T-SB-0058-24 July 8, 2024




# Manual Transmission Unable to Select Second, Fourth, and/or Sixth Gear

Service

**Category** Drivetrain

Section Manual Transmission/Transaxle Market USA



## **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2024	Tacoma	

#### Introduction

Some 2024 model year Tacoma vehicles equipped with a RC60F manual transmission / transaxle may exhibit a condition where the vehicle is unable to shift into second, fourth, and/or sixth gear but is able to shift into all other gears. Further inspection shows signs of cracking from the floor shift control shift lever retainer sub-assembly housing. To address this condition, the manual transmission assembly needs to be replaced. Follow the Repair Procedure in this bulletin to address this condition.

### **Production Change Information**

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	PLANT	DRIVETRAIN	ENGINE	PRODUCTION CHANGE EFFECTIVE VIN
Tacoma	TMMGT	4WD	T24A-FTS	3TYJBAJN#RT028040 3TYLE5JN#RT028040 3TYLB5JN#RT028040 3TYKE5JN#RT028040

**TOYOTA** T-SB-0058-24 July 8, 2024 Page 2 of 3

# Manual Transmission Unable to Select Second, Fourth, and/or Sixth Gear

# **Warranty Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
TC2405	R & R Manual Transmission Assembly	3.8	33030-04080	25	16

#### **APPLICABLE WARRANTY**

- This repair is covered under the Toyota Powertrain Warranty. This warranty is in effect for 60 months or 60,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

#### **Parts Information**

PART N	UMBER	PART NAME	QTY
PREVIOUS	NEW	PART NAIVIE	
33030-04080	33030-04080	Transmission Unit Assy	1

## **Repair Procedure**

1. Confirm the condition exists.

Does the vehicle exhibit a condition where the vehicle is unable to shift into second, fourth, and/or sixth gear but is able to shift into ALL other gears?

- YES Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- 2. Remove the manual transmission assembly.

Refer to TIS, applicable model and model year Repair Manual:

2024 Tacoma:

Drivetrain – RC60F (Manual Transmission / Transaxle) – Manual Transmission Assembly – Removal

3. Remove the floor shift control shift lever retainer sub-assembly.

Refer to TIS, applicable model and model year Repair Manual:

<u>2024</u> Tacoma:

Drivetrain – RC60F (Manual Transmission / Transaxle) – Manual Transmission Unit – Disassembly

**TOYOTA** T-SB-0058-24 July 8, 2024 Page 3 of 3

# Manual Transmission Unable to Select Second, Fourth, and/or Sixth Gear


# **Repair Procedure (continued)**

 Inspect the floor shift control shift lever retainer sub-assembly for the cracking condition.

Does the retainer show signs of cracking as shown in Figure 1?

- YES Continue to step 5.
- NO This bulletin does NOT apply.
  Continue diagnosis using the applicable Repair Manual.

Figure 1. Floor Shift Control Shift Lever Retainer Sub-Assembly



1 Example of Retainer Cracking

- Replace the manual transmission assembly.
  Refer to TIS, applicable model and model year Repair Manual:
  - <u>2024</u> Tacoma:
    Drivetrain RC60F (Manual Transmission / Transaxle) –
    Manual Transmission Assembly Installation
- 6. Test drive the vehicle and confirm the condition no longer exists.