

#1 - LOF SYN: 10K SERVICE, SYNTHETIC 4 CYLINDER
 PERFORM 10000 MILE SERVICE AS RECOMMENDED BY TOYOTA FOR VEHICLES USING FULL SYNTHETIC OIL. INCLUDES LUBE OIL AND FILTER CHANGE, ALSO TIRE ROTATION AND MULTI-POINT INSPECTION.
 REPLACE ENGINE OIL AND OIL FILTER
 Caused by
 AS REQUIRED BY MANUFACTURER.
 Tech: Kevin H. (263)
 Installed: FILTER S/A, OIL 1@5.97
 Installed: GASKET 1@3.20
 Installed: GTMO 0W20 QT SP WTY 8.28 6@8.00
 Hazardous Materials Charge
 COMPLETED. SEE INSPECTION SHEET FOR DETAILS.
 Sub Total: 166.36

104.90
 5.97
 3.20
 48.00
 4.29

#2 - CUST: CUSTOMER STATES
 C/S: TOW IN. DEAD THIS MORNING WOULD NOT GO OUT OF ACC. MODE. PLEASE ADVISE
 Caused by
 c137ba2 brake system control module malfunction.
 freeze frame shows dtc's triggered battery voltage below 11v. vehicle had to be jumped.
 charging system operating. charged battery and tested, failed needs battery replaced

TERMS STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Tech: Ryan B. (205) replaced aux battery with new. Sub Total: .00	
----- #3 - CUST: CUSTOMER STATES C/S: ROOF RACK MAKING NOISE AT 60+ KNOWN ISSUE ON THE FORUMS. PLEASE ADVISE. Caused by added some felt to insulate between faring rubber bushings and mounting bracket. test drove and noise is gone for now. toyota working on repair Tech: James J. (395) Sub Total: .00	
----- #4 - CUST: CUSTOMER STATES C/S: TAILGATE NOT FUNCTIONING AGAIN. REF RO 16369609 PLEASE ADVISE. Caused by this was due to battery voltage dropping. replaced aux battery on previous line and initialized working as designed Tech: James J. (395) Sub Total: .00	
----- #5 * 15TOZ: SERVICE RENTAL ADDED OPERATION	

TERMS STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

DESCRIPTION OF SERVICE AND PARTS	AMOUNT																				
UP TO 2 DAYS COVERED BY SERVICE DEPARTMENT, \$42/DA Y BEGINNING ON THE 3RD DAY. Caused by ACCT # 7502																					
----- #6 * 50TOZ07: *BATTERY REPLACEMENT ADDED OPERATION BATTERY FAILED LOAD TEST BATTERY REPLACEMENT: AUX BATTERY FAILED. EMAILED T O NICOLE Caused by WARRANTY CODE DCAN9880TPSFA0 Tech: James J. (395) Installed: TRUESTART BATTERY Qty: 1 REPLACED BATTERY.	Warranty Warranty																				
----- Toyota CP Variable Discount	-32.00																				
----- Please Note: WAIT WEB CREATED 2024-10-31 02:41:52PM TAKEN BY ***** * Thank you for Choosing Burien Toyota! * * Electrical items are NOT RETURNABLE. All * * returned parts subject to 20% restock fee * *****																					
TERMS STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto." DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.	<table border="1"> <tr><td>LABOR</td><td>104.90</td></tr> <tr><td>PARTS</td><td>57.17</td></tr> <tr><td>DEDUCTIBLE</td><td>.00</td></tr> <tr><td>SUBLET</td><td>.00</td></tr> <tr><td>SHOP SUPPLIES</td><td>.00</td></tr> <tr><td>HAZARDOUS MATERIALS</td><td>4.29</td></tr> <tr><td>SALES TAX OR TAX I.D.</td><td>13.70</td></tr> <tr><td>SPECIAL ORDER DEPOSIT</td><td>.00</td></tr> <tr><td>DISCOUNTS</td><td>-32.00</td></tr> <tr><td>TOTAL DUE</td><td>148.06</td></tr> </table>	LABOR	104.90	PARTS	57.17	DEDUCTIBLE	.00	SUBLET	.00	SHOP SUPPLIES	.00	HAZARDOUS MATERIALS	4.29	SALES TAX OR TAX I.D.	13.70	SPECIAL ORDER DEPOSIT	.00	DISCOUNTS	-32.00	TOTAL DUE	148.06
LABOR	104.90																				
PARTS	57.17																				
DEDUCTIBLE	.00																				
SUBLET	.00																				
SHOP SUPPLIES	.00																				
HAZARDOUS MATERIALS	4.29																				
SALES TAX OR TAX I.D.	13.70																				
SPECIAL ORDER DEPOSIT	.00																				
DISCOUNTS	-32.00																				
TOTAL DUE	148.06																				
NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS. X																					